

# SAFETY RECALL NOTICE

## TROY-BILT TB30 RIDING LAWN MOWERS MODELS: 13AC26JD066



Green X indicates  
good unit



**Products Affected:** Only the model numbers shown above, and within the serial number range, 1G20MB20001 through 1L17MB20228 (manufactured between July 20, 2021 and December 17, 2021), as indicated on your model plate located under the seat, are included in the recall. The second through fifth characters of the serial number identify the manufacturing date. The second character is the month. Months are listed A (January) through L (December). The third and fourth characters are the day of the month. The fifth character is a letter representing the year of manufacture. In this case its letter M for 2021. Also, products with a green “X” on the model plate or products which fall outside the affected serial number range are not affected and are OK to continue using. **Affected products were sold between July 20, 2021 and January 24, 2022.**

**Hazard:** Riding mower may continue to drive at a speed of about (1) mph when clutch/brake pedal is fully depressed posing a potential for a low-speed loss of control or crash.

**What Consumers Should Do:** Consumers should stop using the riding mower and call 1-888-848-6038 for information to obtain service for a replacement drive belt free of charge.

### **DO NOT USE AN AFFECTED PRODUCT**

**If you need assistance locating or reading the model or serial number of your product, or have any other questions, please call our**

**Recall Hotline toll-free at 1-888-848-6038 between 8:30 AM and 5:00 PM EST**

**Monday through Friday**

**Or visit our websites**

**<http://www.mtdproducts.com> or**

**[www.troybilt.com](http://www.troybilt.com) or**

**[www.badcock.com](http://www.badcock.com)**